Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00185

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513					
Exit Meeting Contact: (Not Applicable) Total Man Days: 0						
Pipeline Safety Representative(s): Valerie Schwing						
Company Representative to Receive Report: Michael Fuller	Emailed Date:					
Company Representative's Email Address: mfuller2@ameren.com	06/17/2015					

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection Annual Report Review	ICC Office	Valerie Schwing	Pawnee TRANSMISSION	0	6/2/2015	

Statement of Activities

On June 15, 2015, ICC Staff conducted a review of Ameren Illinois's Annual Reports for calendar year 2014 to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

During the review Staff identified an issue and made contact with Mike Fuller with Ameren Illinois. Staff requested a supplemental report be filed to correct the deficiencies by June 25, 2015.

Exit Statement

INSPECTION FINDINGS

Standard Inspection Annual Report Review

Issues(s) Found:

2015-S001-00025 (Code Part [191.11(a)]) - Staff is questioning the 0 leaks on federal land repaired or scheduled to be repaired for the calendar year 2014 because Ameren Illinois supplies natural gas to Scott Air Force Base which is believed to be federal land. If Ameren Illinois has failed to document these leaks, then Staff requests that Ameren provide training to all locations where a leak can occur on federal land.

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00185

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]